

FIG.1







FIG.2



2/14





3/14





FIG.6

HFG MC


wpwpws





OBLON, SPIVAK, ET AL DOCKET #: 218303US2 INV: Ichiro YOKOZEKI, et al. SHEET _5_ OF_14_

5/14



6/14






FIG.10



7/14



8/14





FIG.13


MC
L2
WP
L4
Wp
L3

FIG.14




AXIAL POSITION OF PRIMARY COIL

FIG.15



10/14








FIG.18



AXIAL POSITION OF HEATING ROLLER

FIG.19









FIG.21






FIG.23

